Leimac Ltd.
LED Lighting Group
Sales Department

TEL: +81-77-585-6771 FAX: +81-77-585-6773

Notice of discontinued product (IDCA-1000M4 series and IDCA-1000M8-S4 controllers)

Due to the global shortage of semiconductors and electronic components, it has become increasingly noticeable that parts and materials are becoming more and more difficult to procure. We will discontinue the IDCA-1000M4 series of constant current controllers and the IDCA-1000M8-S4.

Please consider switching to the recommended alternatives for these products as soon as the parts are no longer available.

We apologize for any inconvenience this may cause and appreciate your understanding.

- Details -

1. Changingover time

IDCA-1000M4 series and IDCA-1000M8-S4 controllers as soon as the materials are run out.

2. Discontinued product and recommended substitutes

Discontinued Product	Recommended substitute product
IDCA-1000M4-VI	IDCA-1000M8-VI
IDCA-1000M4-PI	IDCA-1000M8-PI
IDCA-1000M4-S2	IDCA-1000M8-S2
IDCA-1000M4-S4	-
IDCA-1000M4-TP	IDCA-1000M8-TP
IDCA-1000M8-S4	-

^{*} Recommended substitute product is 8ch type. There is no substitute for the S4 series.

If you have any questions regarding this change, please contact our sales staff.